

Industrial Repair Services of Louisiana ¹

A Manuel & Tedder Enterprise
17188 Airline Highway, Suite M-144
Prairieville, Louisiana 70769

Parts available for the Woodward Systems

Item #	Item Name	Manufacturer	Condition	Quantity Available
2050	P/N 98033-001	Xycom	NEW	1
9448	P/N 9450-2486616010000, options 4668	Xycom	NEW	1
9449	P/N 9450-27B1319010000, options 713332-2.1G	Xycom	NEW	1
9450	P/N 9450-27B1319010000, options 713332-2.1G	Xycom	NEW	1
14HC4AAZ	Model 38-K42IMA-01, MicroVitec	Xycom	NEW	1
1751-147D	4 Channel MPU Transformer	Woodward	NEW	6
1751-6058B	Turbine Control Cards	N/A	N/A	2
1790-789	Intel Memory Card	Woodward	NEW	1
3515 KPM	P/N 3515-A1J204103500V	Xycom	NEW	1
5430-856B	Ext. Card	Woodward	Used	1
5432-039	FSOV Solenoid Drv Mod	Woodward	NEW	4
5432-157	Seq. Power Module	Woodward	NEW	2
5437-281C	LinkNet-FTM Part	Woodward	NEW	3
5437-283C	LinkNet-FTM Part	Woodward	NEW	43
5437-406H	LinkNet-FTM Part	Woodward	U/S	5
5437-417A	LinkNet-FTM Part	Woodward	NEW	2
5437-418	LinkNet-FTM Part	Woodward	Used	1
5437-465C	LinkNet-FTM Part	Woodward	NEW	1
5437-523	LinkNet-FTM Part	Woodward	NEW	1
5437-672F	LinkNet-FTM Part	Woodward	NEW	1
5437-686	LinkNet-FTM Part	Woodward	NEW	5
5438-861	503 Chassis	Woodward	NEW	1
5439-730E	Netco Expansion Chassis P.S.	Woodward	NEW	1
5439-760E	24 VDC Power Supply	Woodward	NEW	1
5439-760H	24 VDC Power Supply	Woodward	Used	1
5439-8000	HV PS Chassis	Woodward	NEW	8
5441-409B	Relay Interface	Woodward	NEW	1
5441-419B	ISO Relay Interface	Woodward	NEW	2
5441-6290	5 Amp Solid State Relay Interface	Woodward	NEW	2
5441-6350	OPTO Isolator	Woodward	NEW	4

Industrial Repair Services of Louisiana
A Manuel & Tedder Enterprise
17188 Airline Highway Suite M-144
Prairieville, Louisiana 70769

Phone: 800-791-1756
Fax: 225-673-6419
Email: sales@irsla.com
Web Site: www.irsla.com

Industrial Repair Services of Louisiana ²

A Manuel & Tedder Enterprise
17188 Airline Highway, Suite M-144
Prairieville, Louisiana 70769

5441-637D	5 Amp Solid State Relay Interface	Woodward	NEW	1
5441-637O	5 Amp Solid State Relay Interface	Woodward	NEW	2
5441-663NW	Solid State Relay Interface	Woodward	NEW	15
5441-689	24/120 I/O	Woodward	Used	1
5441-697A	I/O	Woodward	NEW	1
5448-906C	Control SPM-D10	Woodward	NEW	2
5461-083B/C	Discrete In	Woodward	Used	12
5461-083G	Discrete In	Woodward	Used	1
5461-086	Transducer In	Woodward	NEW	1
5461-086A	Transducer In	Woodward	NEW	4
5461-088DE	DO	Woodward	Used	8
5461-117B	PS A-19	Woodward	NEW	2
5461-331	Master CPU	Woodward	NEW	2
5461-640B	501/503/511/509 Card	Woodward	NEW	1
5461-644H	501/503/511/509 Card	Woodward	NEW	1
5461-644H/G	Turbine Control Cards	N/A	N/A	3
5461-650N	T/C Input	Woodward	NEW	1
5461-653N	501/503/511/509 Card	Woodward	NEW	1
5461-654F/H	8 CH RTD/Input	Woodward	NEW	1
5461-655K	501/503/511/509 Card	Woodward	NEW	1
5461-768O	N1 Speed Control	Woodward	NEW	1
5461-769A	N1 Speed Reference	Woodward	NEW	2
5461-770B	N2 Speed Control	Woodward	NEW	1
5461-771A/O	N2 Speed Reference	Woodward	NEW	2
5461-772A/O	Temp Control	Woodward	NEW	2
5461-773A/B	SW Mode	Woodward	NEW	2
5461-774O	Freq Control	Woodward	NEW	2
5461-775B	Amb Bias Ramp	Woodward	NEW	2
5461-776A/O	Accel Schedule	Woodward	NEW	2
5461-777O	Decel Jump Rate	Woodward	NEW	2
5461-778B	Liq Final Driver	Woodward	NEW	1
5461-779O	Fuel Transfer Card/Board	Woodward	NEW	2

Industrial Repair Services of Louisiana
A Manuel & Tedder Enterprise
17188 Airline Highway Suite M-144
Prairieville, Louisiana 70769

Phone: 800-791-1756
Fax: 225-673-6419
Email: sales@irsla.com
Web Site: www.irsla.com

Industrial Repair Services of Louisiana ³

A Manuel & Tedder Enterprise
17188 Airline Highway, Suite M-144
Prairieville, Louisiana 70769

5461-780B/C	Gas Final Driver	Woodward	Used	2
5461-781O	Synch	Woodward	NEW	2
5461-798O	N1 Speed Control	Woodward	NEW	1
5461-880A	RTD	Woodward	NEW	6
5461-892O	501/503/511/509 Card	Woodward	NEW	1
5461-944C	Speed Control	Woodward	NEW	1
5461-975	Power Supply DCS II LV	Woodward	NEW	1
5461-975J	Power Supply DCS II LV	Woodward	NEW	1
5462-236A	N2 Speed Control	Woodward	NEW	1
5462-244O	Liq Final Driver	Woodward	NEW	1
5462-443	Fuel Transfer Card/Board	Woodward	NEW	1
5462-584	DCS Motherboard	Woodward	NEW	1
5462-758	DCS II Discrete Output	Woodward	NEW	1
5462-896	Turbine Control Cards	N/A	N/A	1
5462-916	DCS II FTC	Woodward	NEW	1
5462-944	DPS3/DT	Woodward	Used	1
5462-948	T/C Fail High	Woodward	NEW	2
5462-948A	T/C Card- 8 Channel	Woodward	NEW	1
5463-124C	SIO	Woodward	NEW	1
5463-140F	Master CPU	Woodward	Used	1
5463-141F	Master CO CPU	Woodward	NEW	1
5463-143	Aux Memory	Woodward	NEW	1
5463-372C	Act Dr	Woodward	NEW	8
5463-373F	A/I Posit	Woodward	NEW	7
5463-375F	A/I Posit	Woodward	NEW	1
5463-384B	A/O 4-20	Woodward	NEW	8
5463-388B	A/I RTD	Woodward	NEW	7
5463-393C	A/I 4-20	Woodward	NEW	13
5463-397C	A/I TC	Woodward	NEW	8
5463-405B	D/I	Woodward	NEW	8
5463-406B	D/O	Woodward	Used	16
5463-408D	A/I Mult	Woodward	NEW	8
5463-431New	A/I RTD	Woodward	NEW	1
5463-436D	Interface	Woodward	NEW	9
5463-450D	CPU	Woodward	NEW	4
5463-473	DCS Ver4, 4 SIO OPSYS	Woodward	NEW	1

Industrial Repair Services of Louisiana
A Manuel & Tedder Enterprise
17188 Airline Highway Suite M-144
Prairieville, Louisiana 70769

Phone: 800-791-1756
Fax: 225-673-6419
Email: sales@irsla.com
Web Site: www.irsla.com

Industrial Repair Services of Louisiana ⁴

A Manuel & Tedder Enterprise
17188 Airline Highway, Suite M-144
Prairieville, Louisiana 70769

5463-474E	CPU Module, 5462-917A	Woodward	NEW	1
5463-482B	Turbine Control Cards	N/A	N/A	1
5463-531B	Turbine Control Cards	N/A	N/A	1
5463-561D	Circuit Board	Woodward	NEW	1
5463-578D	CPU	Woodward	NEW	1
5463-579	FC 109 Master Co-Pro	Woodward	NEW	1
5463-716A	SIO	Woodward	NEW	3
5463-785J	Turbine Control Cards	N/A	N/A	2
5463-786F	Turbine Control Cards	N/A	N/A	1
5463-834A	Turbine Control Cards	N/A	N/A	1
5463-870NW	2C Act Driver	Woodward	Used	1
5463-877H	4 Channel P Driver	Woodward	NEW	1
5463-881G	CPU	Woodward	NEW	4
5463-887J	ISOL T/C FH	Woodward	NEW	1
5464-013G	2C Act Driver	Woodward	Used	1
5464-018O	DIG Spd	Woodward	NEW	9
5464-021A	SIO	Woodward	NEW	5
5464-050	SQ 109 Master CPU	Woodward	NEW	1
5464-114O	Turbine Control Cards	N/A	N/A	1
5464-210D	2C Act Driver	Woodward	NEW	1
5464-210E	2C Act Driver	Woodward	NEW	1
5464-211D	2C Act Driver	Woodward	NEW	1
5464-212B	2C Act Driver	Woodward	NEW	1
5464-213K	SIO Phase 3B	Woodward	NEW	1
5464-213M	SIO Phase 3B	Woodward	NEW	1
5464-333F	ISO T/C High In	Woodward	NEW	1
5464-333H	ISOL T/C FH 11489606	Woodward	NEW	3
5464-334E	Turbine Control Cards	N/A	N/A	4
5464-337	Semi ISO RTD 100	Woodward	NEW	9
5464-428B	A/I 4-20	Woodward	NEW	2
5464-458A	D/O	Woodward	NEW	1
5464-552B	2C Act Driver	Woodward	NEW	1
5464-555A	2C Act Driver	Woodward	NEW	1
5464-645B	2C Act Driver	Woodward	NEW	1
5464-646	2C Act Driver	Woodward	Used	14
5464-646C	2C Act Driver	Woodward	NEW	1
5464-655B	4 Channel P Driver	Woodward	NEW	1

Industrial Repair Services of Louisiana
A Manuel & Tedder Enterprise
17188 Airline Highway Suite M-144
Prairieville, Louisiana 70769

Phone: 800-791-1756
Fax: 225-673-6419
Email: sales@irsla.com
Web Site: www.irsla.com

Industrial Repair Services of Louisiana ⁵

A Manuel & Tedder Enterprise
17188 Airline Highway, Suite M-144
Prairieville, Louisiana 70769

5464-676	XCVR	Woodward	NEW	3
5464-697A	CPU Module	Woodward	Used	1
5464-716A	SIO	Woodward	Used	1
5464-827NEW	CPU Module	Woodward	NEW	1
5464-830B	A/I 4-20	Woodward	NEW	1
5464-836A	Remote XCVR	Woodward	NEW	3
5466-006A	Turbine Control Cards	N/A	N/A	1
5466-017	2C Act Control	Woodward	NEW	3
5466-033E	CPU Module	Woodward	NEW	1
5466-041	2C Pos Control	Woodward	NEW	8
5466-042C	CPU Module	Woodward	NEW	1
5466-045F	Pressure Transducer Interface	Woodward	NEW	1
5466-272	SOLND Mon	Woodward	NEW	7
5466-336	SIO	Woodward	NEW	1
5500-134NEW	Ext. Card	Woodward	NEW	1
5500-559D	Buffer Board	Woodward	NEW	1
5501-469B	CPU	Woodward	Used	1
5501-469C	CPU	Woodward	NEW	1
5503-335	CPU	Woodward	NEW	2
8200-169G	EM Digital Driver	Woodward	NEW	1
8200-220	Servo Position Control	Woodward	NEW	2
8200-314	GS/LQ Digital Driver, LQ25 Valve, 382A4818P0001	Woodward	Used	2
8220-805D	Final Driver	Woodward	NEW	1
8230-805C	Final Driver IGV	Woodward	Used	1
8230-883C/O	Final Driver IGV/VSV	Woodward	NEW	12
8230-896A	Final Driver-Water	Woodward	NEW	6
8230-898A	Final Driver	Woodward	Used	1
8236-144D	Light Panel	Woodward	NEW	1
8271-472	2301 Load Sharing & Speed Control	Woodward	NEW	1
8271-472D	2301 Load Sharing & Speed Control	Woodward	NEW	1
8271-872D	Import/Export Control	Woodward	NEW	1
8272-447	Motor Operated Pot	Woodward	NEW	2
8272-695	Real Power	Woodward	Used	1
8272-781A	Real Power Sensor	Woodward	NEW	1

Industrial Repair Services of Louisiana
A Manuel & Tedder Enterprise
17188 Airline Highway Suite M-144
Prairieville, Louisiana 70769

Phone: 800-791-1756
Fax: 225-673-6419
Email: sales@irsla.com
Web Site: www.irsla.com

Industrial Repair Services of Louisiana ⁶

A Manuel & Tedder Enterprise
17188 Airline Highway, Suite M-144
Prairieville, Louisiana 70769

8273-276	377A7823P0001, Atlas PC 2x4, SC w/act, LV, 2EBX	Woodward	NEW	1
8434-246C/E	Main Chassis with LED & P.B.	Woodward	NEW	8
8923-811	Kit-Read Only Ladder Logic V1.04 Kit	Woodward	NEW	1
9905-020R	Low Voltage 2301 Load Sharing & Speed Control	Woodward	NEW	1
9905-204H	Synchronizer	Woodward	NEW	1
9905-603	Digital Synch & Load Control	Woodward	NEW	1
9905-678	Turbine Control Cards	N/A	N/A	3
9905-707	DSL Control	Woodward	Used	1
9905-708	Digital Synch & Load Control	Woodward	NEW	25
9905-760NEW	LinkNet Module	Woodward	Used	1
9905-970J	LinkNet Module	Woodward	NEW	3
9905-971J	LinkNet Module	Woodward	Used	1
9905-972F	LinkNet Module	Woodward	NEW	1
9906-124E	Real Power Sensor	Woodward	NEW	2
9907-005L	377A62602P0001, 9905-713F	Woodward	NEW	1
9907-031	Transducer	Woodward	NEW	2
9907-124	Real Power	Woodward	Used	1
9907-126	EM-35 Digital Driver	Woodward	Used	6
9907-135D	GS/LQ Driver S/N 13360427/12399976 (Rev C)	Woodward	NEW	N/A
9907-186	GS10 Driver	Woodward	NEW	1
9907-331	DLE Press Transducer with Papers	Woodward	Used	1
9907-624B	EM35 Digital Driver (9907-126 at 10000)	Woodward	Used	1
9907-963	DLE Press Transducer with Papers, PT 62105A/136A/138A/137A	Woodward	Used	1
PM 9451	9450-27B1319010000	Xycom	NEW	1

All parts provided by Industrial Repair Services of Louisiana come with a One-Year Warranty.

Pricing is subject to change at any time, please contact Industrial Repair Services for most recent pricing and availability. Inventory and pricing may change due to our stock and cost for repair parts needed.

Industrial Repair Services of Louisiana
A Manuel & Tedder Enterprise
17188 Airline Highway Suite M-144
Prairieville, Louisiana 70769

Phone: 800-791-1756
Fax: 225-673-6419
Email: sales@irsla.com
Web Site: www.irsla.com

Industrial Repair Services of Louisiana ⁷

A Manuel & Tedder Enterprise
17188 Airline Highway, Suite M-144
Prairieville, Louisiana 70769

Industrial Repair Services of Louisiana provides spare parts and repairs for most major makes of PLC, DCS and Control Systems.

Industrial Repair Services of Louisiana does not sell or provide software licensing for any items sold. All software is property of the original manufacturer and must be purchased from them directly. All firmware and proprietary information is sole property of the OEM and we do not provide or sell any such items.

Industrial Repair Services of Louisiana
A Manuel & Tedder Enterprise
17188 Airline Highway Suite M-144
Prairieville, Louisiana 70769

Phone: 800-791-1756
Fax: 225-673-6419
Email: sales@irsla.com
Web Site: www.irsla.com